


SpinBox Encoder Hardware Kit Assembly Guide






Step 1: Put *TWO* 10-32 x 1.25" Screws (am-1041) into the SpinBox Housing (am-2456) mounting holes.





Step 2: Slide the CIM Spacer (am-0555) in place through the screws.




Note:

The CIM Spacer allows for an encoder to fit onto the housing without any interference.





Step 4: Place the 0.475" Long Nylon Spacer (am-0925) onto the CIM Motor shaft followed by the 0.375" Long Spacer



Tip:

Place the machine key after the spacers have been inserted

You may now continue with **Step 4 on the **
standard SpinBox Assembly instructions