




Wiring (Front)



Wiring (Back)

This Hall Effect sensor will be pulled low when a magnet is sensed and be high impedance when a magnet is not present. Use this as a limit switch.